PH 01.06.03

Qty:

Each

1 Um:

: BASKET BASE ASSEMBLY (350)

: D2221

: N/A

: F/B1

: 10/06/2008

SAO

: D2221 U/R, D2235

■Date: User: Monday, 02/06/2008 4:38:08 PM

Julie Lecocq

Process Sheet

Drawing Name

Part Number

Material

Due Date

Drawing Number

Project Number

Drawing Revision

Customer

: CU-DAR001 Dart Helicopters Services

Type

S.O. No. :

Job Number **Estimate Number**

: 39652A : 10189

P.O. Number

This Issue Prsht Rev. : 02/06/2008

: NC

First Issue : // : 39529C

Previous Run

Written By

Checked & Approved By

Comment

: Est Rev:J 05.09.02 Added D3442-1KJ/JLM

: LARGE FAB ASSY

6.03

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description: **Basket Hoop**

1.0 D31661



Comment: Qty.: 4.0000 Each(s)/Unit Total:

4.0000 Each(s)

Description Batch **Qty Part Number**

RIB D3166-1 D22323

2.0

Pick:

Basket Hinge

2.0000 Each(s)

Comment: Qty.:

2.0000 Each(s)/Unit Total:

Pick: **Qty Part Number**

2 D2232-3 Hinge bracket <u>336346</u>

Description Batch

3.0

D2325

Support Gusset (350 Basket)

Comment: Qty.: 4.0000 Each(s)/Unit Total: 4.0000 Each(s)

Pick:

Qty Part Number 4 D2325 Support Gusset

Description Batch

4.0 D23273

Spacer Bushing



Comment: Qty.: 2.0000 Each(s)/Unit Total: 2.0000 Each(s)

Pick:

Qty Part Number

Description Batch

2 D2327-3 Bushing

108.04.25

22

Dart Aerospace Ltd

W/O:		WORK ORDER CHA	WORK ORDER CHANGES							
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
				•						
		······································								
Part No	:	PAR #: Fault Category:	NCR: Yes	No DQ	A :	Date:				
			QA:	N/C Close	d:	_ Date: _				

NCR:			WORK ORDER NON-CONFORMANCE (NCR)							
		Description of NC		Corrective Action Section B				Ι		
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	Approval QC Inspector		
						•				
							į			
						-				
		110000000000000000000000000000000000000								

NOTE: Date & initial all entries

Date: Monday, 02/06/2008 4:38:08 PM User: Julie Lecocq **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: BASKET BASE ASSEMBLY (350) Job Number: 39652A Part Number: D2221 Job Number: Seq. #: Machine Or Operation: Description: D2581 5.0 Mounting Bracket Comment: Qty.: 2.0000 Each(s)/Unit Total: 2.0000 Each(s) Pick: **Qty Part Number** Description Batch Mounting Bracket 33904 2 D2581 D34421 Comment: Qty.: 2.0000 Each(s)/Unit Total: 2.0000 Each(s) Pick: Batch B37615 Description **Qty Part Number** 2 D3442-1 Shim 7.0 M304EX07516F Expanded Metal Flat Stai Comment: Qty.: 41.6745 sf(s)/Unit Total: 41.6745 sf(s) Pick: Description Batch Qty Part Number 08-06-25 39.69 sf M304EX0.75-16F Expanded Metal <u>P1108152</u> 8.0 M304TS0750W065 304 SQ Tube.75x.75x.065W Comment: Qty.: 29.4000 f(s)/Unit Total: 29.4000 f(s) , 0.065 PH 08.06.03 Pick: 3/4" x 3/4" x 0.063 wall 304/316 SStubing Batch: M101063 "4" 71/30/80 708153 LARGE FABRICATION RESOURCE 1 9.0 LARGE FAB Comment: LARGE FABRICATION RESOURCE 1 SAN 08/06/17 Q 1-Cut D2235-1 Rib from D3166-1 Rib As Per Dwg D2235 2-Drill hole in D2221-3 as per Dwg D2221 3-Deburr 4-Remove all markings on material before welding 5-Weld as per Dwg D2221 using Welding Table and corner JigDeburr as required

Page 2

W/O:			WORK ORDER CHANGES							
DATE	STEP	PF	OCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
				·						
Part No	•	PAR #:	Fault Category:	NCR: Ye	s No DQ	A:	Date: _			
				QA:	N/C Close	d:	Date: _			

NCR:			WORK ORD	ER NON-CONFORMANC	E (NCR)							
		Description of NC		Corrective Action Section B		Verification	Annroyal	Approval QC Inspector				
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng					
	1			,								
•												

NOTE: Date & initial all entries

Monday, 02/06/2008 4:38:08 PM Date: User: Julie Lecocq **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: BASKET BASE ASSEMBLY (350) Job Number: 39652A Part Number: D2221 Job Number: Seq. #: **Machine Or Operation:** Description: QC9 10.0 VISUAL WELDING INSPECTION **Comment: VISUAL WELDING INSPECTION** 11.0 QC6 DIMENSIONAL CHECK Comment: DIMENSIONAL CHECK 12.0 POWDER COATING POWDER COATING Comment: POWDER COATING Powder Coat White Gloss (Re START TIME: **OVEN TEMPERATURE** FINISH TIME: 13.0 QC3 INSPECT POWDER COAT/CHEMICAL CONVE Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION FINAL INSPECTION/W/O RELEASE 14.0 QC21 Comment: FINAL INSPECTION/W/O RELEASE Job Completion

Dart Aerospace Ltd

W/O:			WC	ORK ORDER CHANG	SES			
DATE STEP		PR	PROCEDURE CHANGE By				Approval Chief Eng / Prod Mgr	Approval QC inspector
				•				
Part No	:	PAR #:	Fault Cate	gory:	NCR: Yes	No DQA:	Date: _	
					QA: N	/C Closed:	Date: _	
NCR:			WORK ORDI	ER NON-CONFORM	ANCE (NCF	()		
		Description of NC	Corrective Action Section B			Verification	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Section C	Chief Eng	QC Inspector
	1				. Oh.			

NOTE: Date & initial all entries

DAVIT

DESIG	BW	DRAWN BY	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA
CHEC	KED	APPROVED AL	DRAWING NO. REV. F
	#	M	D2221 SHEET 1 OF 3
DATE			TITLE SCALE
05.0	06.07		BASKET BASE ASSEMBLY (350) NTS
С		95.11.21	SEPARATE BASKET AND LID
D		96.06.21	CHANGE LATCH
Ε		01.04.19	CHANGE HINGE
F		05.06.07	ADD SHIM UNDER HINGES, ADD HOLES FOR SPLIT LID BASKETS

OS 08.19

PARTS LIST FOR D2221 BASKET BASE ASSEMBLY

PART NO	QUANTITY	LENGTH	LENGTH	DESCRIPTION
	,	Α	В	
D2221-1	2		96.00	RIB
D2221-3	2		25.50	RIB
D2221-5	2	18.88		RIB
D2221-7	1	55.25	<u></u>	RIB
D2232-3	2	N/A	N/A	HINGE PLATE
D2235-1	4	N/A	N/A	RIB
D2325	4	N/A	N/A	SUPPORT GUSSET
D2327-3	2	N/A	N/A	BUSHING
D2581	2	N/A	N/A	MTG BRKT
D3442-1	2	N/A	N/A	SHIM

B 45°

RETURN TO
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT

WITHOUT NOTICE WORK ORDER

D2221-1/-3/-5/-7

1) CUT LENGTH/SHAPE PER DIAGRAM AND PARTS LIST

2) MATERIAL: AISI 304/316 SS, 3/4 X 3/4 X 0.060 WALL SQUARE TUBING (REF. DART SPEC M304TS0.750W 060)


- 3) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) ALL DIMENSIONS ARE IN INCHES
- 5) DRILL Ø0.257 HOLES ONLY WHEN ASSEMBLING D2221 BASE WITH D2989-041/-043 BASKET LID

Copyright @ 1994 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.



DESIGN BW	DRAWN BY PH	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	-
CHECKED	APPROVED A	DRAWING NO.	REV. F
#	#	D2221 SHEET	3 OF 3
DATE		TITLE	SCALE
05.06.07		BASKET BASE ASSEMBLY (350)	1:8





DRILL 3/8 HOLE AND INSTALL D2327-3 USING CLOSEST SPACE IN EXPANDED METAL FOR HOLE LOCATION BOTH ENDS

> SHOP COPY RETURN TO **ENGINEERING**

WITHOUT NOTICE

SECTION A-A SAME BOTH END RIBS






SECTION B-B SAME BOTH CENTER RIBS

Copyright @ 1994 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.



(1)